



RO Name: Fuelmate Filling station

Date: 2026-02-26

Audit Score:

10 / 19

Morning Operations

Density Taken & Recorded	<input checked="" type="checkbox"/> YES
Stock Dipping Done	<input checked="" type="checkbox"/> YES
Stock Board Updated	<input checked="" type="checkbox"/> YES
Automation System Online	<input checked="" type="checkbox"/> NO
Measurement Test (5L)	<input checked="" type="checkbox"/> YES

Safety Checks

Fire Extinguishers Check	<input checked="" type="checkbox"/> YES
Sand Buckets Clean & Dry	<input checked="" type="checkbox"/> YES
Aluminum Bucket & Bonding Wire Check	<input checked="" type="checkbox"/> YES
Emergency Switch Tested	<input checked="" type="checkbox"/> NO

Clean RO & Staff

Forecourt Cleanliness	<input checked="" type="checkbox"/> YES
Staff in Proper Uniform	<input checked="" type="checkbox"/> NO
Staff Promptness/Behavior	<input checked="" type="checkbox"/> YES
Washroom Cleanliness	<input checked="" type="checkbox"/> NO
Water & Shop Available in Toilet	<input checked="" type="checkbox"/> YES

Customer Feedback



TEST CUSTOMER (FM01FM1450)

Rating: 5/5

TEST CUSTOMER 1 (FM01FM0999)

Rating: 5/5

SUPPORT OFFER (FM01FM0699)

Rating: 5/5

Manager Signature:

